



## **SCRATCH/STONECHIP REPAIR GUIDE**

- 1 REMOVE FLAKING PAINT AND CLEAN THE REPAIR AREA WITH PRECLEANER.
- 2 SHAKE THE COLOUR WELL AND APPLY TO THE STONECHIP OR SCRATCH. A SECOND APPLICATION CAN BE MADE IF REQUIRED 30 MINUTES AFTER THE FIRST .ALLOW THE PAINT TO DRY THOROUGHLY (2 HOURS APPROX)
- 3 WHEN THE PAINT IS DRY APPLY 2 OR 3 COATS OF LACQUER. THE STONE CHIP IS NOW REPAIRED. WHEN REPAIRING A SCRATCH MAKE SURE THE LACQUER LEVEL ENDS UP ABOVE THE EXISTING PAINTWORK. LEAVE THE LACQUER FOR 24 HOURS TO ENSURE IT IS PROPERLY HARDENED.
- 4 FOR SCRATCHREPAIRS, WHEN THE LACQUER IS HARD, FOLD SOME OF THE FLATTING PAPER AROUND THE RUBBING BLOCK AND DIP IN WATER, GENTLY RUB ALONG THE SCRATCH TO ACHIEVE A SMOOTH FLAT SURFACE.[DO NOT RUB IN A CIRCULAR MOTION] IF THE LACQUER ISN'T NOW LEVEL WITH THE EXISTING PAINTWORK AND THERE ARE A NUMBER OF DIPS VISABLE, CLEAN THE AREA THOROUGHLY AND REAPPLY THE LACQUER AND ALLOW 24 HOURS TO DRY, AND THEN REPEAT THE FLATTING PROCESS. NEVER OVER FLAT TO GET RID OF DIPS AS YOU MAY OVERTHIN THE EXISTING LACQUER.
- 5 USING THE POLISHING CLOTH (SLIGHTLY DAMPEN CLOTH) RUB SOME LIQUID COMPOUND OVER THE AREA IN A CIRCULAR MOTION. THIS WILL BRING BACK THE GLOSS AND MAKE THE FLATTING MARKS DISAPPEAR. BUFF WITH A DRY CLOTH.